



# IMPORTANT PRODUCT DESIGN INFORMATION

In May 2007, Opel/Vauxhall fitted a modified flywheel at the point of vehicle production, the modification resulted in the flywheel pot depth changing from 19mm to 21.6mm, therefore a new clutch kit was also required. Some vehicles produced before May 2007 that suffered from the symptoms of clutch grab were retrofitted with the modified flywheel at the dealership workshops, these vehicles had a green dot painted onto the gearbox linkage housing, to identify this modification.

The following clutch kits and CSC clutch kits must be paired with the correct flywheel that is fitted or to be fitted to the vehicle. The table below shows the correct flywheel / kit combination.

19mm Pot Depth - OES 55587033  
No groove around circumference of flywheel



Corresponds to JT7362, JT7362014,  
JT7362026, JT73621083

21.6mm Pot Depth - OES 55587031  
Grove around circumference of flywheel



Corresponds to JT1639, JT16391083

Vehicle Applications:

OPEL Astra-G,H, Combo-B, Corsa-C, Meriva-A, Vectra-B,C, Zafira-A,B  
VAUXHALL Astra IV,V, Combo II, Corsa II, Meriva I, Vectra I,II, Zafira I,II



**Need more support?**

For comprehensive advice from one of our clutch experts, email [TGLSales@tibbettsgroup.com](mailto:TGLSales@tibbettsgroup.com)